

# Split Rock Lighthouse Historic Structures Report

*Great Lakes*

The 106 Group worked with the Minnesota Historical Society and a local architect on this reknown Minnesota landmark on the North Shore of Lake Superior. The study included an historic structures report, finishes analysis, conservation assessment, and training of site staff on the building's physical history and proper building maintenance for the lighthouse keepers' houses and associated outbuildings. All work was conducted in compliance with the Secretary of the Interior's Standards for the Treatment of Historic Properties.



Minnesota Historical Society